



10/ 036 027

IFW/CYC
PATENT
6,813,421

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant(s): Lail et al.

**CERTIFICATE OF
CORRECTION**

Group Art Unit: 2874

Patent No.: 6,813,421 ✓
Issued: November 2, 2004
For: FIBER OPTIC CABLE HAVING A RIPCORD

Examiner: Pak, Sung H.

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

This is a request for the issuance of a Certificate of Correction for the above patent. Two (2) copies of the special Form PTO 1050 are enclosed. The complete Certificate of Correction involves one (1) page.

The errors occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Issuance of the Certificate of Correction under Rule 322 containing the correction is earnestly requested.

Respectfully submitted,

Date:

4/15/05

Michael E. Carroll, Jr.
Attorney for Assignee
Reg. No. 46,602
Corning Cable Systems LLC
PO Box 489
Hickory, NC 28603-0489
(828) 901-6725

Date of Deposit:

April 18, 2005

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being deposited with the United States Postal Service on the date indicated above with sufficient postage as first class mail in an envelope addressed to the: Commissioner for Patents, PO Box 1450, Alexandria, VA 22313-1450.

Signature

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,813,421

DATED : November 2, 2004

INVENTOR(S) : Lail et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Claim 11, Lines 5-6 delete "and being operative"

Claim 11, Line 8 insert - -and the ripcord being operative- - before the word "upon"

MAILING ADDRESS OF SENDER:

Michael E. Carroll, Jr.
Corning Cable Systems LLC
PO Box 489
Hickory, NC 28603-0489

PATENT NO.: 6,813,421

No. of additional copies